

File: Arrcom, Inc.

ID 0961  
8.28.85  
44

RECEIVED  
OCT 08 1985

NARRATIVE INSPECTION REPORT IDAHO OPERATIONS OFFICE

RCRA Compliance Inspection

Rec'd RO  
12/24/85  
Rec'd RCRA Comp  
2/6/86

Facility: Arrcom, Inc.

Date of  
Inspection: August 28, 1985

EPA I.D. No.: IDD000800961

Address: 5 miles east of State line, Highway 53  
Rathdrum, ID 83858

Report Prepared by: Patrick W. Stoll  
Senior Hazardous Materials Specialist  
IDHW/DOE, Bureau of Hazardous Materials  
Statehouse  
Boise, ID 83720-9990

Inspector: Patrick W. Stoll  
IDHW/DOE  
Bureau of Hazardous Materials  
Telephone: (208) 334-4722

PURPOSE:

The purpose of the inspection was to determine compliance status of the facility under 40 CFR 265.

GENERAL FACILITY DESCRIPTION:

Arrcom, Inc., originally notified EPA of on-site storage, treatment, and/or disposal of hazardous waste. A Part A RCRA permit application was submitted for the facility on November 17, 1980. The facility initially qualified for interim status under RCRA to store and treat ignitable hazardous waste and spent solvents. On June 20, 1982, an inspection conducted by the EPA at the facility found that hazardous waste or hazardous waste constituents had been spilled and/or disposed of on-site.

An EPA Complaint and Compliance Order issued on April 27, 1983, required Arrcom, Inc., to submit a Part B RCRA permit application within 180 days of their receipt of the Order. On May 27, 1983, the facility owner submitted a letter to EPA stating that the facility was not to be used for the handling of hazardous waste in the future. The letter also clarified the intention of the facility owner not to submit a RCRA Part B permit application. At that time, EPA proposed to terminate interim status for the facility. The period for public comment in regards to the termination of interim status began on May 18, 1984, and ended on July 2, 1984.

USEPA RCRA  
  
3009286

(3) Has owner/operator established financial assurance for the post-closure care of the facility (40 CFR 265.145)? YES ☒ NO

(4) By what method has this been achieved:

- (a) Trust fund
- (b) Surety bond (with standby trust)
- (c) Letter of credit (with standby trust)
- (d) Insurance
- (e) Financial test
- (f) Corporate guarantee
- (g) Multiple Mechanisms

( )  
( )  
( )  
( )  
( )  
( )  
( )

none  
↓


(5) Has owner/operator submitted an originally signed duplicate of financial assurance to Regional Administrator?

YES ☒ NO


(6) Is wording of the financial assurance statement identical to that specified in 40 CFR 264.151?

YES ☒ NO





ARRCOM, INC. EPA ID# IDD000800961  
RATHDRUM, IDAHO



SITE ENTRANCE (DIRECTLY  
ADJACENT TO STATE HIGHWAY 53)  
WITH SECURITY CLOSURE.  
AUGUST 28, 1985